

WHAT IS CLAIMED IS:

sub
C1

1. A method of monitoring, analyzing and managing
mechanical press usage, comprising:
monitoring vibration severity, including vibration
severity zone;
monitoring tipping moment severity;
monitoring press repair information, including die
repair information;
monitoring press maintenance information, including die
maintenance information;
monitoring press applied load; and
analyzing the effect of vibration severity, tipping
moment severity, press repair, press maintenance and applied load
to determine necessary press modifications.

10

Add
B1